







PRODUCT / PRODUCTO: COLUMBIA PUMPS (ATB motor)

MOTOR	HP	230V	230/400V
ATB	0,75	32770	32771
ATB	1	32772	32773
ATB	1,5	32774	32775
ATB	2	32776	32777
ATB	3	32778	32779



PRODUCT / PRODUCTO: COLUMBIA PUMPS (ATB motor)

MOTOR	HP	230V	230/400V
ATB	0,75	32770	32771
ATB	1	32772	32773
ATB	1,5	32774	32775
ATB	2	32776	32777
ATB	3	32778	32779





CURVAS CARACTERÍSTICAS PERFORMANCE CHARTS

PRODUCT / PRODUCTO: COLUMBIA PUMPS (ATB motor)

MOTOR	HP	230V	230/400V
ATB	0,75	32770	32771
ATB	1	32772	32773
ATB	1,5	32774	32775
ATB	2	32776	32777
ATB	3	32778	32779

